



## Silver Jewelry

A jewelry manufacturer was out of compliance with several metals including lead and silver. Their flushing cleaning water produces wastewater with levels over 100 ppm of lead and silver. By changing the treatment process and adding Floccin A, the facility has been in compliance (lead < 1 ppm, silver < 2 ppm) consistently.

